




*Section 22 Rehabilitation Alternatives Analysis and
Environmental Permitting*

*Contract 7155
Quarterly Update*

July 22, 2020



Project Schematic





Test Pit Status









LEGEND		
STATUS	PIPE CONDITION	SOIL CONDITION
 Incomplete	 Good	 Mildly Aggressive Corrosivity
 Complete	 Fair	 Aggressive Corrosivity

FIGURE 1
MWRA Distribution Pipes
Sections 21 & 22
TEST PIT STATUS



Section 21 Sample from Test Pit #6






*Lynnfield Center Water District:
Emergency Connection*

July 22, 2020



Lynnfield Center Water District





*New Positions for
Metropolitan Tunnel Redundancy Department*

July 22, 2020




Tunnel Department Org - July 2018

Tunnel Redundancy Program Department

Proposed Organizational Chart

July 18, 2018






Tunnel Department Org - September 2018

Tunnel Redundancy Program Department

Organizational Chart

September 20, 2018






Tunnel Department Org - October 2019

Tunnel Redundancy Program Department

Organizational Chart


October 16, 2019





Tunnel Redundancy

July 22, 2020






***Update on Early Warning Pilot for the
Resurgence of COVID-19
Biobot***

July 22, 2020




Most Recent Results: Viral Titers





Most Recent Results: Deer Island





Most Recent Results: Headworks

